25X1

25X1

ماد ... 25X1 CONFIDENTIAL CENTRAL INTELLIGENCE AGENCY 25X1A INFORMATION REPORT COUNTRY Gratemals REPORT NO. SUBJECT Puerto Barrios, Petroleum Terminal Marine Facilities RESPONSIVE TO PLACE ACOULRED 25**X**1A 25X1A DATE ACOULDED DATE DISTR. 4 JUNE 34 DATE (OF INFO.) NO. OF PAGES NO. OF ENCLS. ITS CONTENTS TO OR RECEIPT BY AN UNAUTHORIST PERSON BY LAR. THE REPRODUCTION OF THIS REPORT IS PROHIBIT SUPP. TO THIS IS UNEVALUATED INFORMATION REPORT NO. 25X1X 1. . Puerto Barrios is on the Atlantic side of Guatemala at the Rast side of the entrance to Santo Tomas Bay in Lat 15043' N Long 83036' W. H O Chart 2. The facilities consist of a long steel pier which extends in a west erly direction from where for a distance of 2,200 feet with berthing spaces for dry cargo vessels on both sides of the pier. There is however, only one tanker berth which is located at the south side outer and of the pier with 24 ft of water alongside; 24 ft is also the controlling depth entering the port. Oil connections are located 270 ft from the outer end of the pier and refined products are discharged through one - 8" line with a water slug between each grade discharged. An additional 6" line for refined products in 1952 in the process of being installed, which would step up turnaround of vessels considerably. This dork is suitable to accommodate vessels of the T-2type as there are good facilities for mooring. Such vessels' draft mast, however, be Limited to 23 ft or less. Vessels dock port side to without tugs as there are none available and none are needed. Pilots are also unavailable. The meun rise and fall of tide is seven inches, and the times of high and low water are largely affected by winds. Yessel Mesters should take no lee that a mortherly current which sets diagonally across the end of the dock may be experienced due to the discharge of water from the rivers into the head of Santo Tomas Bay. At this location ME trade winds prevail; they are strongest from May to September, during which period there are frequent heavy squalls at night accompanied by thunder and lightning. Vessels must be well secured to the dock while discharging cargo.

4. Since this is primarily a dry cargo terminal some delays in waiting berth may be experienced from time to time.

LIBRARY SUBJECT & AREA CODES

-end-

35E . 35E

CONFIDENTIAL

JUBBC. DISTRIBUTION - CTATE ·NAVY AIR FBI

This report is for the use within the USA of the Intelligence components of the Departments or Agencies indicated above. It is not to be transmitted overseas without the concurrence of the originating office through the Assistant Director of the Office of Collection and Dissemination, CIA.

25X1

Approved For Release 2003/12/18: CIA-RDP80-00809A000500510142-5